



MB02 from 8BC - redrawn by Suksoft 2017 version 1.1

Use this gate is a bug! Use I011F instead of I011E